7-11-11

DATE:



TENNESSEE DEPARTMENT OF TRANSPORTATION **EROSION PREVENTION/SEDIMENT CONTROL** INSPECTION REPORT

Reason For Inspection:

	_
(1st	Weekly
-	

2nd Weekly

											DAIL.	
										A1. 1. 1	ti t (\//\\\):	r
State Route (SR) / US Route or Road Name and Description:						Are corrective actions required by this inspection report (Y/N):						
Wolf River Blvd.								YE 5	-			
County(ies)		TDOT PIN:	T I	NPDES Per	rmit (NOC)	#.	Number of	New	Number of	Recurring	Number of New	Number of Un-Corrected
7 10 12			19				Corrective		Corrective		Sediment Releases:	Sediment Releases:
SI	helby	1016	15	7	NR153299						*	
TDOT Cons	struction No.:	TDOT Contra	ct No.:	Contractor:		8	3		6			
7994-	-1535-54			Acuff	Enterprise	s Inc.			Ь			
	er penalty of law					COG EPS	C Inspector	and Title (p	rint or type)	:	Signature:	,
A Comment of the Comm	der my direction	Night and Court property in single or some son filtering		acame alika resultation alika was a re-							1 2 1 #	1
	assure that quali						Gera	ld "Jerry" S	tanfill		Do a Stant	
	oresented. Base system, or those						Dest of the					
	I cerify that inspe					Contractor EPSC Inspector and Title (print or type): Signature:					^	
	nd sediment cont											()
l.	tify that erosion a			•		Tom Acuff						De 11/1/2
	tfall where install			. 24		COG EPSC Project Manager Signature:					1000	
	he table above.											
knowing viole		including the po	issibility of th	ie and impre	somment for	r (print or type):						K.//
iniowing viol	ations.					Timothy Bierdz					(Couly 1)	
		·									1/	
		TDOT EPSO	: Inspectio	n Weekly R	Rainfall Da	ta Log						
		Predicted	Rainfall	Rainfall	Rainfall	Rainfall	Rainfall	Rainfall		TDOT/Co	ntractor Agrees with Ir	nspection Report:
Date	Day of Week	Precipitation	Gauge 1	Gauge 2	Gauge 3	Gauge 4	Gauge 5	Gauge 6	Duration	NO	or (YES)	
		(%)	(in)	(in)	(in)	(in)	(in)	(in)	(hr)	If No, exp	lain and initial:	333
	Sunday				N/A	N/A	N/A	N/A				-
7/11/11	Monday	10	0	0	N/A	N/A	N/A	N/A		Con	merting 1	actions on
7/12/11	Tuesday	30			N/A	N/A	N/A	N/A				
7/13/11	Wednesday	40			N/A	N/A	N/A	N/A		RI	ogness.	
7/7/11	Thursday	30			N/A	N/A	N/A	N/A	100h - 175,055,011 sa		(11 04	
7/8/11	Friday	30	0.60	0.90	N/A	N/A	N/A	N/A	3.0			

Predicted Precipitation Source:

10

0

Friday

Saturday

Sunday

Monday

7/10/11

N/A

N/A

N/A

www.weather.com

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Page 1 of 8

(Additional pages may be attached, if needed)

OBEAT SE	AGRIC	HE WAS A SECOND	URE	
••	1	796	37	

State/US Route or Road Name:	Wolf River Blvd.
otateroo Route of Road Name.	VVOII IXIVEI DIVU.

TDOT Construction No.: 79954-3537-54

	-353	

TDOT Contract No.:

Date	7/11/2011	

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
1	1	14+14	LT	6/3/2011		22,35	S	STABLE (NO ACTION NEEDED)
1A	1	21+50	RT	7/5/2011	T = 3-25-11	33,35	S	Correction has been made. See photo
1B	1	22+00	RT	6/20/2011	T= 3-25-11	24,33,35	S	STABLE (NO ACTION NEEDED)
1C	1	21+00	LT	7/8/2011	T = 3-25-11	10,12,16,35	FM	The perimeter needs additional mulch. Once haul road is established. See photo
2A	1	33+50	LT	7/11/2011		16,24	S	STABLE (NO ACTION NEEDED)
2B	1	35+50	LT	7/11/2011		16,24	I, RO	Incomplete, remove felled trees from stream. See Photo
3	1	34+50	LT			W. S. B.	S	The area has not been disturbed.
4	1	40+00	RT	7/11/2011		16	S	STABLE (NO ACTION NEEDED)
5A	1	49+00	RT				S	The area has not been disturbed.
5B	1	50+00	RT				S	The area has not been disturbed.

EROSION AND SEDIMENT CONTROL MEASURE CODES

1	Temporary Silt Fence / Filter Barrier	15		29	Excess Dirt Removed from Rdwy. Daily	M	Maintenance
2	Temporary Diversion Berm or Ditch	16	Temporary Mulch	30	Haul Roads Dampened for Dust Control	U	Upgrade Needed (Failure Noted)
3	Temporary Slope Drain	17	Erosion Control Blanket	31	Ditch Liner	R	Replacement Needed
4	Rock Check Dams	18	Flexible Channel Liner	32	Rock Silt Screen	FM	Future Maintenance
5	Brush Barrier	19	Catch Basin / Storm Inlet Protection	33	Temporary Silt Fence with Backing	С	Cleaning Needed
6	Sediment Removal	20	Riprap Outlet Structure	34	Enhanced Silt Fence	1	Increase Measures
7	Straw Bale Check	21	Riprap Energy / Velocity Dissipater	35	Sediment Tube	W	Too Wet to Work Conditions
8	Sand Bags	22	Curb, Gutter, or Storm Sewer Protection	36	Sediment Dam	RO	Repeat Occurrence
9	Sediment Trap / Basin	23	Temporary at Construction Exit / Entrance	37	Concrete Washout, other pollution Issues	SR	Sediment Release
10	Temp Sediment Filter Bag / Dewatering	24	Temporary Stream Crossing	38	Berm (soil, riprap, rock)	FS	Final Stabilized
11	Polyethylene Sheeting	25	Turbidity Barrier / Silt Boom	39	Gabion	S	Stable (No Action Needed)
12	Machined Rip Rap	26	Temporary Stream Diversion	40	Sheet Pilling	Other (O31):	
13	Geotextile	27	Preserve Natural Resource / Buffer Zone	41	Haul Road	Other (O#2):	
14	Permanent Seeding with Mulch or Sod	28	Mineral Aggregate Base on Subgrade	42		Other (O#3):	

CONDITION CODES

Stat	e/U	S F	Rou	te

State/US Route or Road Name:	Wolf River Blvd.	TDOT Construction No.:	79954-3537-54	TDOT Contract No.:

Date	7/11/2011

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
5C	1	44+00	LT				S	The area has not been disturbed.
6	1	56+00	LT				S	The area has not been disturbed.
7	1	60+00	RT				S	The area has not been disturbed.
8A	1	73+00	RT				S	The area has not been disturbed.
8B	2	75+50	RT	7/5/2011		16,35	S	Stable (No action needed)
8C	1	71+00	LT				S	The area has not been disturbed.
8D	2	75+50	LT	7/5/2011		16,35	S	Stable (No action needed)
8E	1	71+50	LT				S	The area has not been disturbed.
9A	2	80+00	RT	7/11/2011		16,35	I,RO	Incomplete, stabilize and remove temp. dirt dam after construction, each day. See Photo
9B	2	80+00	LT	7/11/2011	20.000	16,35	ı	Additional BMP's required. See Photo

EROSION AND SEDIMENT CONTROL MEASURE CODES

CONDITION CODES Temporary Silt Fence / Filter Barrier Temporary Seeding with Mulch Excess Dirt Removed from Rdwy. Daily Maintenance 2 Temporary Diversion Berm or Ditch 16 Temporary Mulch 30 Haul Roads Dampened for Dust Control U Upgrade Needed (Failure Noted) 3 Temporary Slope Drain 17 Erosion Control Blanket 31 Ditch Liner R Replacement Needed Rock Check Dams 18 Flexible Channel Liner 32 Rock Silt Screen FM **Future Maintenance** Brush Barrier 19 Catch Basin / Storm Inlet Protection Temporary Silt Fence with Backing C Cleaning Needed 33 Sediment Removal 20 **Enhanced Silt Fence** 6 Riprap Outlet Structure 34 Increase Measures Straw Bale Check 21 Riprap Energy / Velocity Dissipater 35 Sediment Tube W Too Wet to Work Conditions Sand Bags 22 Curb, Gutter, or Storm Sewer Protection RO 8 36 Sediment Dam Repeat Occurrence Sediment Trap / Basin 23 9 Temporary at Construction Exit / Entrance 37 Concrete Washout, other pollution Issues SR Sediment Release Temp Sediment Filter Bag / Dewatering 10 24 Temporary Stream Crossing 38 Berm (soil, riprap, rock) FS Final Stabilized S 11 Polyethylene Sheeting 25 Turbidity Barrier / Silt Boom 39 Gabion Stable (No Action Needed) 12 Machined Rip Rap 26 Temporary Stream Diversion 40 Sheet Pilling Other (O31): Other (O#2): 13 27 41 Geotextile Preserve Natural Resource / Buffer Zone Haul Road Permanent Seeding with Mulch or Sod Mineral Aggregate Base on Subgrade 42 Other (O#3):

State/US		

Wolf River Blvd.

TDOT Construction No.:

79954-3537-54

TDOT Contract No.:

Date 7/11/2011

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
9C	2	79+50	LT	7/11/2011	r – reini.	16,35	1	Additional BMP's Required. See Photo
10A	2	85+00	RT	7/11/2011	T = 5-31-11	16,24,35	s	Currently stable, Monitoring BMP's
10B	2	85+00	RT	7/11/2011	T = 5-31-11	16,24,35	s	Corrections have been made.
10C	2	85+50	LT	7/8/2011	T = 5-31-11	16,35	M,RO	Incomplete, Remove construction floatables and stabilize. See Photo
10D	2	84+50	LT	7/8/2011	T = 5-31-11	10,16,35	I,RO	Stockpile too close to work zone/stream and stabilize.
11A	2	92+50	RT	7/11/2011	T = 5-31-11	16,24,35	FM	Remove temp. rock dam at end of each day after construction. See Photo
11B	2	92+50	LT	7/11/2011	T = 5-31-11	10,35	I,RO	Stockpile too close to work zone/stream and stabilize. See photo
11C	2	92+00	LT	7/11/2011	T = 5-31-11	35	I,RO	Stockpile too close to work zone/stream and stabilize. See photo (sheet 7 of 8). Also, need to remove construction and domestic floatables from stream. See photos (see sheet 8 of 8).
M-1900 REC. 15. 1.15. 51	1	11+28	LT	6/27/2011	T = 6-3-11	19,35	FM	Currently stable, Monitoring BMP's
	1	13+40	RT	7/5/2011		23,29,30	FM	Daily cleaning will be required, until further notice.
	1	107+75	CL	7/5/2011		23,29,30	FM	Daily cleaning will be required, until further notice.
		FROSIO	N AND SEDIME	NT CONTROL N	MEASURE CODES			CONDITION CODES

	EROSION	I AND	SEDIMENT CONTROL MEASURE C	ODES			CONDITION CODES
1	Temporary Silt Fence / Filter Barrier	15	Temporary Seeding with Mulch	29	Excess Dirt Removed from Rdwy, Daily	M	Maintenance
2	Temporary Diversion Berm or Ditch	16	Temporary Mulch	30	Haul Roads Dampened for Dust Control	U	Upgrade Needed (Failure Noted)
3	Temporary Slope Drain	17	Erosion Control Blanket	31	Ditch Liner	R	Replacement Needed
4	Rock Check Dams	18	Flexible Channel Liner	32	Rock Silt Screen	FM	Future Maintenance
5	Brush Barrier	19	Catch Basin / Storm Inlet Protection	33	Temporary Silt Fence with Backing	C	Cleaning Needed
6	Sediment Removal	20	Riprap Outlet Structure	34	Enhanced Silt Fence	1	Increase Measures
7	Straw Bale Check	21	Riprap Energy / Velocity Dissipater	35	Sediment Tube	W	Too Wet to Work Conditions
8	Sand Bags	22	Curb, Gutter, or Storm Sewer Protection	36	Sediment Dam	RO	Repeat Occurrence
9	Sediment Trap / Basin	23	Temporary at Construction Exit / Entrance	37	Concrete Washout, other pollution Issues	SR	Sediment Release
10	Temp Sediment Filter Bag / Dewatering	24	Temporary Stream Crossing	38	Berm (soil, riprap, rock)	FS	Final Stabilized
11	Polyethylene Sheeting	25	Turbidity Barrier / Silt Boom	39	Gabion	S	Stable (No Action Needed)
12	Machined Rip Rap	26	Temporary Stream Diversion	40	Sheet Pilling	Other (O31):	
13	Geotextile	27	Preserve Natural Resource / Buffer Zone	41	Haul Road	Other (O#2):	
14	Permanent Seeding with Mulch or Sod	28	Mineral Aggregate Base on Subgrade	42		Other (O#3):	

ننزد	OF THE ST	
	APA !	
	GRICULTURE	
Ŋ.	0MMERC 1796	

State/US Route or Road Name:	Wolf River Blvd.	TDOT Construction No.:	79954-3537-54	TDOT Contract No.:

Date	7/11/2011

Outfall Name or Station No. *(Existing Structure)	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
* 109+51	2	East side of WRB	RT	7/5/2011	193	19,22	FM	Stable, monitoring BMP's.
* 109+11	2	South side of Farmington	RT	7/5/2011		19,22	FM	Stable, monitoring BMP's.
* 12+80	1	North side of WRB	LT	7/5/2011	000000000000000000000000000000000000000	19,22	FM	Stable, monitoring BMP's
	1	23+25	LT	7/5/2011			FM	Daily monitoring required.
	2	75+00	CL	7/11/2011		16	FM	Additional stabilization required. See Photo
	2	107+30 - 107+50	LT	7/11/2011		16,35,41	С	Remove excess concrete. See Photo
		16.5	· 200 / 200					
			1777		4.0001/-000/	A STATE OF THE STA	Account the same and same same same same same same same same	

EROSION AND SEDIMENT CONTROL MEASURE CODES

Temporary Silt Fence / Filter Barrier 1 15 Temporary Seeding with Mulch Excess Dirt Removed from Rdwy. Daily M Maintenance Temporary Diversion Berm or Ditch 2 16 Temporary Mulch 30 Haul Roads Dampened for Dust Control U Upgrade Needed (Failure Noted) 3 Temporary Slope Drain 17 **Erosion Control Blanket** 31 Ditch Liner R Replacement Needed 4 Rock Check Dams Flexible Channel Liner 18 Rock Silt Screen FM **Future Maintenance** 5 Brush Barrier 19 Catch Basin / Storm Inlet Protection Temporary Silt Fence with Backing С Cleaning Needed 6 Sediment Removal 20 Riprap Outlet Structure 34 Enhanced Silt Fence Increase Measures 7 Straw Bale Check 21 Too Wet to Work Conditions Riprap Energy / Velocity Dissipater 35 Sediment Tube W 8 Sand Bags 22 Curb, Gutter, or Storm Sewer Protection Repeat Occurrence 36 Sediment Dam RO 9 Sediment Trap / Basin 23 Temporary at Construction Exit / Entrance 37 Concrete Washout, other pollution Issues SR Sediment Release Temp Sediment Filter Bag / Dewatering 10 24 Temporary Stream Crossing 38 Berm (soil, riprap, rock) Final Stabilized FS 11 Polyethylene Sheeting 25 Turbidity Barrier / Silt Boom 39 Gabion S Stable (No Action Needed) 12 Machined Rip Rap 26 Temporary Stream Diversion 40 Sheet Pilling Other (O31): Other (O#2): 13 Geotextile 27 Preserve Natural Resource / Buffer Zone 41 Haul Road Permanent Seeding with Mulch or Sod Other (O#3): 14 28 Mineral Aggregate Base on Subgrade 42

CONDITION CODES



Outfall 1A Sta. 21+50 RT Correction has been made.



Outfall 1C Sta. 21+00 LT
Construction activity is in the process of beginning installing a haul road. Therefore, future maintenance is required. (FM)



Outfall 2B Sta. 35+50 LT Incomplete, remove felled trees from stream. (I,RO)



Outfall 9A Sta. 80+00 RT Incomplete, stabilize and remove temp. dirt dam after construction each day. (I,RO)



City of Germantown 1920 S. Germantown Road Germantown, TN 38138




Outfall 11B Sta. 92+50 LT and Outfall 11C Sta. 92+00 LT Stockpiles to close to stream and stabilize.
(I,RO)

Outfall 11A Sta. 92+50 RT Remove temp. rock dam at end of each day after construction. (FM)



City of Germantown 1920 S. Germantown Road Germantown, TN 38138





City of Germantown 1920 S. Germantown Road Germantown, TN 38138